

Prepared for :

**Identified 29 Snags**



dublinsnaglist.com

Front door not closing correctly

Weather strip to bottom needs replacing at front door

Crack below glass panel at front door – fill and repaint



Back garden hole in the ground to be refilled



## **EXTERNAL CONTINUED:**

Damage to window reveal at back and plaster to be cleaned from sill



Cement on waste pipe needs cleaning



Adhesive on fascia/socket at side of house







## **INTERNAL**

### **ENSUITE**

No running water

Door not closing properly



Photo	Snags Title / Assign To / Description	Created / Fix By Date	Status
 <p>04-05-2018 10:43:53</p>	<b>Issue 1 exterior</b> Electrical box doors not fitted Front door to be cleaned	04-05-2018	Open
 <p>04-05-2018 10:44:02</p>	<b>Issue 2</b> Threshold to be cleaned Back garden not seeded	04-05-2018	Open
	<b>Issue 3 third floor</b> Window board sand fill and repaint	04-05-2018	Open
	<b>Issue 4 3rd floor</b> Fill skirting to wall and repaint	04-05-2018	Open